


Multiple Displacement Solenoid

MAKE A BETTER REPAIR | INCLUDES O-RINGS AND MOUNTING BOLT

**PREMIUM O-RINGS ENSURE PROPER SYSTEM PRESSURE****INCLUDES NEW MOUNTING BOLT****HOUSING AND PLUNGER BOTH UPGRADED FROM BRITTLE PLASTIC TO DURABLE, HEAT-RESISTANT ALUMINUM TO HELP IMPROVE RELIABILITY****916-592XD**

Chrysler 2021-10, Dodge 2021-10, Jeep 2021-10, Ram 2021-11

- Troubleshooting the symptoms of a failing MDS requires inspection of all four of the engine's MDS solenoids, whose fragile housings often break during removal from the engine
- Satisfy your customers with a more permanent and cost-effective repair with this upgraded MDS design

4WD Auto Locking Hub Assembly

IMPROVED DESIGN | MAKE A BETTER REPAIR

**SHIFT DIAL WITHSTANDS 40% MORE TORQUE THAN FACTORY DESIGN****IMPROVED DRY ROT RESISTANT RUBBER DIAPHRAGM****600-203XD**

Ford 2005-99 Super Duty, Expedition, Excursion, Lincoln Navigator 2002-01

- Subjected to 15+ performance tests, including tests for salt spray corrosion, extreme cold durability, and thermal cycling
- Make a more robust repair for OE 4WD locking hub on specified Ford and Lincoln pickups and SUVs with broken shift dial

Electric Engine Water Pump

UPGRADED HOUSING FOR A BETTER REPAIR | SEAMLESSLY INTEGRATES WITH BMW ECM

**UPDATED CIRCUIT BOARD INCREASES RELIABILITY****INCLUDES NEW MOUNTING BOLTS****UPGRADED ALUMINUM HOUSING****599-962**

BMW 2017-07

- Matches the fit, function and performance of the original BMW water pump
- Laboratory and on-vehicle road testing includes validation of dimensions, connector fitment, flow rates and thermal shock durability

Pre-Pressed Rear Axle (Rear Right)

AFTERMARKET EXCLUSIVE | TIME-SAVING SOLUTION

**NO SHOP PRESS NEEDED****BOLT-ON SOLUTION**
CAN SAVE 90+ MINUTES WHEN REPLACING DIFFICULT PRESS-IN WHEEL BEARINGS**READY TO INSTALL**
INCLUDES AXLE, BEARING, BACKING PLATE, BOLTS AND SEALS**926-148**

Toyota Tundra 2006-00

- Turn your bays faster with this exclusive, pre-assembled axle for aging Toyota Tundras
- Make a safe, predictable repair with no shop press or fabrication of specialized tooling required



NEW MUST-SEE SOLUTIONS

OUR LATEST INNOVATIONS THAT
SERVICE PROFESSIONALS NEED TO KNOW ABOUT

Diesel Fuel Filter Housing

AFTERMARKET EXCLUSIVE | **DIRECT REPLACEMENT**



**FITMENT TESTED FOR A
HASSLE-FREE INSTALLATION**

904-000

Chevrolet Silverado 2016-11, GMC Sierra 2016-11

Engine Fuel Line (Rear)

AFTERMARKET EXCLUSIVE | **DIRECT REPLACEMENT**



904-012

Chevrolet Silverado 2014-04, GMC Sierra 2014, GMC Sierra 2010-04

Loaded Magnetic Strut Assembly (Front)

**DIRECT REPLACEMENT
NO SPRING COMPRESSOR REQUIRED
FOR INSTALLATION**



949-730

Cadillac 2020-15, Chevrolet 2020-15, GMC 2020-15
Various GM Trucks and SUVs

Keyless Entry Keypad

AFTERMARKET EXCLUSIVE | **DIRECT REPLACEMENT**



601-046

Ford 2020-15 F-150 and Super Duty

Magnetic Ride Control Shock (Rear)

AFTERMARKET EXCLUSIVE | **DIRECT REPLACEMENT**



949-705

Cadillac 2019-15, Chevrolet 2019-15, GMC 2019-15
Various GM Trucks and SUVs

